

**CDM Post Operations Analysis 20.01.2023**

CDM for Date: 20.01.2023 CDM Name: CDM1_VIDP_200123 Applicable Airport: VIDP Time (UTC): 0600 – 0900
Reason: DUE DEMAND CAPACITY IMBALANCE CAUSED BY IAF REPUBLIC DAY EXERCISE Max. Delay (Mins.): 52 Average Delay (Mins.): 10

CDM ANALYSIS						Flights Operated But Not Captured in SKYFLOW
ATFM MEASURES	GSP1 (0600-0645)	GDP1 (0645-0700)	GDP2	GDP3		AIC446(VILH-VIDP)
DURATION (From – To in UTC)	0600-0700		(0700-0800)	(0800-0900)		
Predicted demand of Arrival (Skyflow)	10		44	45		
No. of Arrivals Planned for this Period	5		40	43		
Actual Arrivals (As per SKYFLOW)	2		38	43		
Manual CTOTs (Nos.)						16
Compliance (%)						98.44
Accuracy (%)						92.77

NOTE: Accuracy of the CDM is the hourly callsign wise comparison between the predicted flights during preparation of CDM with flights actually operated. It is measured in percentage (%)

DETAILS OF CTOT NON-COMPLIANT FLIGHTS							
Call sign	ADEP	EOBT	ETOT	CTOT	Revised EOBT	Revised manual CTOT	System ATOT
AIC880	VEBD	06:40	06:45	07:06			06:42



CTOT NON-COMPLIANCE SUMMARY			
Airport		Airline	
Airport Name	Total Number	Operator Name	Total Number
VEBD	01	AIRINDIA	01

CDM OBSERVATIONS / FEEDBACK	
Traffic Flow:	Smooth
Substantial Holdings (>15 Mins.):	NIL
Diversions (If Any):	NIL
Any Unanticipated Events:	NIL
Flight Data Issue:	NIL
Airspace Data Issue:	NIL
Any Other Relevant Issues / Remark:	VTI884 (VOCI-VIDP), RELEASED BY COCHIN ATC BEFORE ISSUANCE OF CTOT, INSPITE OF PRIOR COORDINATION BY ATFM

TEAM-B

Prepared by (Officer's Sign., Name & Designation)

VINAY KUMAR, AGM (ATM-ATFM)

Operations Shift Supervisor (Sign., Name & Desig.)