

CDM Post Operations Analysis 13.04.2023

CDM for Date:	13/04/2023	CDM Name:	CDM1_VIDP_130423	Applicable Airport:	VIDP	Time (UTC):	0600-0730	
Reason:	Hindon Airspace Restriction	Max. Delay (Mins.):	24	Average Delay (Mins.):	04	_		

	CDM ANALYSIS			Flights Operated But Not Captured in SKYFLOW
ATFM MEASURES	GDP1 (0600-0630)	GDP2 (0630-0730)		
DURATION (From – To in UTC)	0600-0700	0700-0730		
Predicted demand of Arrival (Skyflow)	42	18		
No. of Arrivals Planned for this Period	32	15		
Actual Arrivals (As per SKYFLOW)	35	22		
Manual CTOTs (Nos.)				9
Compliance (%)				93
Accuracy (%)				100

NOTE: Accuracy of the CDM is the hourly callsign wise comparison between the predicted flights during preparation of CDM with flights actually operated. It is measured in percentage (%)

DETAILS OF CTOT NON-COMPLIANT FLIGHTS							
Call sign	ADEP	EOBT	ETOT	стот	Revised EOBT	Revised manual CTOT	System ATOT
IAD798	VEGT	03:45	03:50	03:58			03:48
IGO2982	VISR	06:00	06:05	06:29			05:44

CCC/CATFM/v3.0/13-04-2023 Page | 1



CTOT NON-COMPLIANCE SUMMARY				
Airpo	rt	Airline		
Airport Name	Total Number	Operator Name	Total Number	
VEGT	1	INDIGO	1	
VISR	1	AIR ASIA	1	

CDM OBSERVATIONS / FEEDBACK			
Traffic Flow:	SMOOTH		
Substantial Holdings (>15 Mins.):	NIL		
Diversions (If Any):	NIL		
Any Unanticipated Events:	NIL		
Flight Data Issue:	NIL		
Airspace Data Issue:	NIL		
Any Other Relevant Issues / Remark:	Hindon airspace available at 0605		

TEAM C	Ashroni Voncen ACNA/ATNA ATENA)
TEAM - C	Ashwani Kumar, AGM(ATM-ATFM)
Prepared by (Officer's Sign., Name & Designation)	Operations Shift Supervisor (Sign., Name & Desig.)

CCC/CATFM/v3.0/13-04-2023 Page | 2