

**CDM Post Operations Analysis 28.04.2025**

CDM for Date: 28/04/2025 CDM Name: CDM3_VIDP_280425 Applicable Airport: VIDP Time (UTC): 0900-1300
Reason: RWY 10/28 ILS CAT3 UPGADATION
WIP and EASTERLY MODE OF OPERATIONS Max. Delay (Mins.): 67 Average Delay (Mins.): 18

	CDM ANALYSIS									Flights Operated but Not Captured in CDM
ATFM MEASURES	GDP1/GDP2/GDP3/GDP4									
DURATION (From – To in UTC)	0900-1000		1000-1100		1100-1200		1200-1300		SHIFTED TO NEXT HOUR (1300-1400)	
Predicted demand of Arrival (Skyflow)	Current	Carryforward (previous hrs)	Current	Carryforward (previous hrs)	Current	Carryforward (previous hrs)	Current	Carryforward (previous hrs)	32	
	46	04	36	16	32	18	50	16		
No. of Arrivals Planned for this Period	34		34		34		34			
Actual Arrivals (As per SKYFLOW)	35		26		34		35			
Manual CTOTs (Nos.)										18
Compliance (%)										95
Accuracy (%)										96

NOTE: Accuracy of the CDM is the hourly callsign wise comparison between the predicted flights during preparation of CDM with flights actually operated. It is measured in percentage (%)

DETAILS OF CTOT NON-COMPLIANT FLIGHTS							
Call sign	ADEP	EOBT	CTOT	Revised EOBT	Revised manual CTOT	System ATOT	Reason for Non- Compliance (as reported by ATC)
AIC2770	VECC	0710	0809			0728	EMERGENCY HANDLING AT VECC
AIC462	VIAR	1045	1151			1131	RUNWAY CLOSURE
AXB1103	VERC	0825	0910			0855	CTOT NOT RECEIVED
IGO205P	VOTV	0700	0741			0703	CTOT NOT RECEIVED
IGO2081	VELP	0830	0925		0835	0822	BAD WEATHER



LLR632	VEAB	1050	1151			1103	CTOT NOT RECEIVED

CTOT NON-COMPLIANCE SUMMARY

Airport			Airline	
Airport Name	Total Number		Operator Name	Total Number
VECC	01		AIR INDIA	02
VIAR	01		AIR INDIA EXPRESS	01
VERC	01		ALLIANCE AIR	01
VOTV	01		INDIGO	02
VELP	01			
VEAB	01			

CDM OBSERVATIONS / FEEDBACK

Traffic Flow:	SMOOTH
Substantial Holdings (>15 Mins.):	NIL
Diversions (If Any):	NIL
Any Unanticipated Events:	NIL
Flight Data Issue:	NIL
Airspace Data Issue:	NIL
PRI Lines (Status):	SERVICEABLE (Outgoing Calls Only)
Any Other Relevant Issues / Remark:	NIL

TEAM-B
Prepared by

DHANRAJ MEENA, Jt.GM (ATM-ATFM)
Operations Shift Supervisor