

CDM Post Operations Analysis 24.03.2023

CDM for Date:	24/03/2023	CDM Name:	CDM1_VIDP_240323	Applicable Airport:	VIDP	Time (UTC):	0600-0800	
Reason:	DEMAND CAPACITY IMBALANCE	Max. Delay (Mins.):	31	Average Delay (Mins.):	06			
_	CAUSED BY ILS CALIBRATION			_				

	CDM ANALYSIS				Flights Operated But Not Captured in SKYFLOW	
ATFM MEASURES	C	GDP1				AIC412(VILK- VIDP)
DURATION (From – To in UTC)	0600-0700	0700-0800				
Predicted demand of Arrival (Skyflow)	43	28				
No. of Arrivals Planned for this Period	33	32				
Actual Arrivals (As per SKYFLOW)	26	34				
Manual CTOTs (Nos.)						14
Compliance (%)						94
Accuracy (%)						96

NOTE: Accuracy of the CDM is the hourly callsign wise comparison between the predicted flights during preparation of CDM with flights actually operated. It is measured in percentage (%)

DETAILS OF CTOT NON-COMPLIANT FLIGHTS							
Call sign	ADEP	EOBT	ETOT	стот	Revised EOBT	Revised manual CTOT	System ATOT
GOW226	VILH	0510	0515	0527			0544
IGO7325	VEPT	0630	0635	0658			0631
LLR806	VICG	0515	0520	0521			0533
		_			_		
		_			_		



CTOT NON-COMPLIANCE SUMMAR			
A	irport		
Airport Name	Total Number	Operato	
VEPT	01	GC	
VICG	01	IG	
VILH	01	LL	

Airline			
Operator Name	Total Number		
GOW	01		
IGO	01		
LLR	01		

CDM OBSERVATIONS / FEEDBACK				
Traffic Flow:	SLIGHT HOLDING DUE WEATHER			
Substantial Holdings (>15 Mins.):	NIL			
Diversions (If Any):	NIL			
Any Unanticipated Events:	WEATHER			
Flight Data Issue:	NIL			
Airspace Data Issue:	NIL			
Any Other Relevant Issues / Remark:	NIL			

TEAM - C

Prepared by (Officer's Sign., Name & Designation)

Ashwani Kumar, AGM(ATM-ATFM)

Operations Shift Supervisor (Sign., Name & Desig.)