

**CDM Post Operations Analysis 27.03.2023**

CDM for Date: 27/03/2023 CDM Name: CDM1_VIDP_270323 Applicable Airport: VIDP Time (UTC): 0600-0800
Reason: DUE ILS CALIBRATION OF RWY 27 Max. Delay (Mins.): 22 Average Delay (Mins.): 03

	CDM ANALYSIS				Flights Operated But Not Captured in SKYFLOW
ATFM MEASURES	GDP1	GDP2			
DURATION (From – To in UTC)	0600-0700	0700-0800			
Predicted demand of Arrival (Skyflow)	33	40			
No. of Arrivals Planned for this Period	32	32			
Actual Arrivals (As per SKYFLOW)	24*	35			
Manual CTOTs (Nos.)					6
Compliance (%)					90.20
Accuracy (%)					96.42

NOTE: Accuracy of the CDM is the hourly callsign wise comparison between the predicted flights during preparation of CDM with flights actually operated. It is measured in percentage (%)

DETAILS OF CTOT NON-COMPLIANT FLIGHTS							
Call sign	ADEP	EOBT	ETOT	CTOT	Revised EOBT	Revised manual CTOT	System ATOT
AIC446	VILH	0630	0635	0642			0655
IGO66555	VISR	0615	0620	0630			0718
SEJ8374	VISR	0625	0630	0643			0720
SEJ8939	VEGK	0615	0620	0630			0643
T7RSP	VOBG	0400	0405	0416			0449



CTOT NON-COMPLIANCE SUMMARY			
Airport		Airline	
Airport Name	Total Number	Operator Name	Total Number
VISR	2	INDIGO	1
VILH	1	SPICE JET	2
VEGK	1	AIRINDIA	1
VOBG	1	NON SKD	1

CDM OBSERVATIONS / FEEDBACK	
Traffic Flow:	SMOOTH
Substantial Holdings (>15 Mins.):	NIL
Diversions (If Any):	NIL
Any Unanticipated Events:	NIL
Flight Data Issue:	NIL
Airspace Data Issue:	NIL
Any Other Relevant Issues / Remark:	* FROM 0638- 0658 UTC, AFTN MESSAGES AND ASM FEED(DELHI RADAR) WAS NOT AVBL DUE TECHNICAL

TEAM - D

Prepared by (Officer's Sign., Name & Designation)

D Guha Roy, Jt. GM(ATM-ATFM)

Operations Shift Supervisor (Sign., Name & Desig.)